

Mercedes-Benz E 250

VIN: W1K1771861J232948

Generat pe 2024-11-25 08:47



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

✓ Arată bine



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **8 țări**: +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Lituania



Statele Unite ale Americii



Slovacia



Finlanda



Italia



Slovenia




Suedia

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

Notă

Ultimul kilometraj cunoscut: 58.909 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?

✓ **Nu s-au găsit probleme**

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?

✓ **Nu s-au găsit probleme**

Înregistrări de daune



Ocazional pot apărea inexactități, mai ales la verificarea vehiculelor vechi. Atelierele clandestine de reparații pot deghiza ilegal defectele sau daunele vehiculelor, fără să declare nicăieri existența lor. Uneori până și plăcuțele VIN ale vehiculului pot fi înlocuite. Avem o varietate de metode de a detecta chiar și astfel de infracțiuni, dar este imposibil de oferit o garanție de 100%.

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?

Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Mercedes-Benz



Model

E 250



Tip caroserie

Sedan



An model

2020



Capacitate cilindrică

1,4 l



Putere motor

84 kW (113 cp)



Cutie de viteze

Automată



Amplasarea volanului

Volan pe stânga

Echipare

02B

OPERATING INSTRUCTIONS AND SERVICE BOOKLET-GERMAN

02J

INVALID CHANGEOVER OF WORLD MANUFACTURER TO MERCEDES-BENZ AG (ASF)

050

YOM X9/2

085

WORLD MANUFACTURER CONVERSION TO MERCEDES-BENZ AG

08U

MERCEDES-BENZ CONNECT - SERVICES FOR VEHICLE SETUP (HERMES)

09U

MERCEDES-BENZ CONNECT - VEHICLE MONITORING (HERMES)

13U

MERCEDES-BENZ CONNECT - EV FUNCTIONS

14U

SMARTPHONE INTEGRATION PACKAGE

16U

APPLE CARPLAY SMARTPHONE INTEGRATION

17U

ANDROID AUTO SMARTPHONE INTEGRATION

189

CHANGEOVER OF CO2MPAS-3

1B3

COMMUNICATION MODULE ECE VERSION

1U5

RUBBER-SPRUNG STEERING GEAR

218

REAR VIEW CAMERA

229L

GERMANY

235

ACTIVE PARKING ASSIST

243

ACTIVE LANE KEEPING ASSIST (CAMERA)

249

AUTOMATIC DIMMING INSIDE REARVIEW MIRROR AND OUTSIDE MIRRORS

255B

MB-MOBILIO WITH DSB AND GGD

258

COLLISION WARNING SYSTEM WITH FCW-STOP ACTIVE BRAKE APPLICATION

270

GPS AERIAL

286

LUGGAGE NETS TO LEFT AND RIGHT DRIVER SEAT BACKRESTS

287

THROUGH-LOADING FEATURE

294

KNEEBAG

2R9

WINTER WHEEL AND TIRE ASSEMBLY - LIGHT ALLOY 10-SPOKE DESIGN 17"

2U1

RADIATOR SHUTTER

2U8

ALTERNATIVE REFRIGERANT

2XXL

FEDERAL REPUBLIC OF GERMANY

310

DOUBLE CUP HOLDER

320A

FABRIC

321A

FABRIC - BLACK / ANTHRACITE

332B

LANGUAGE OF INSTRUMENT CLUSTER/HU - GERMAN

345

RAIN SENSOR

351

ECALL EMERGENCY CALL SYSTEM

355

PREINSTALLATION FOR RETROFITTING NAVIGATION SYSTEM

362

HERMES COMMUNICATIONS MODULE LTE

365

HARD DRIVE NAVIGATION

367

PRE-INSTALLATION FOR LIVE TRAFFIC INFORMATION

3U6

HU COUNTRY SET FOR ECE/ROW

426

AUTOMATIC DUAL-CLUTCH TRANSMISSION, 8-SPEED

428

STEERING WHEEL GEARSHIFT BUTTONS/STEERING WHEEL GEARSHIFT PADDLES - PAINTED

440

CRUISE CONTROL

446

TOUCHPAD ONLY

458

INSTRUMENT CLUSTER DISPLAY S

475

TIRE PRESSURE MONITOR (TPM)

485

COMFORT SUSPENSION

500

ELECTRICALLY FOLDING EXTERIOR MIRRORS

502

MULTI-YEAR FREE MAP UPDATES

513

ROAD SIGN RECOGNITION SYSTEM

51B

RATING, COUNTRY GROUP EURO-NCAP

51U

HEADLINER, BLACK FABRIC

543

SUN VISOR WITH ADDITIONAL FUNCTION

548

CONNECT 20 MID (NTG6)

580

AIR-CONDITIONING SYSTEM

608

AUTOMATIC HIGH BEAM CONTROL (IHC)

632

HEADLAMPS, LED, STATIC, RIGHT-SIDE TRAFFIC

63B

VEHICLE SOCKET XEV COMBO 2/TYPE 2

651

WINTER TYRES FITTED

66R

LIGHT-ALLOY WHEEL 5-DOUBLE-SPOKE DESIGN 18" ALL-ROUND

696J

NIGHT BLACK - STANDARD FINISH

6P5

CONTROL CODE FOR SALES

70B

SAFETY VEST - DRIVER

79B

PRE-INSTALLATION FOR DIGITAL RADIO STANDARD DAB/DMB

7U2

SEAT MODEL VARIANT 2

800

YOM X9/1

80B

SINGLE-PHASE LOW AC CHARGING FUNCTION (3.2 KW-3.8 KW)

853

MIDLINE SOUND SYSTEM

859

CENTRAL DISPLAY SIZE M

871

HANDS-FREE ACCESS

873

SEAT HEATERS FOR DRIVER AND FRONT PASSENGER

877

AMBIENT LIGHTING

889

KEYLESS-GO

8U6

ASSISTANCE SYSTEM STEERING WHEEL CONTROL CHANGEOVER

8U8

I-SIZE MARKING (ISOFIX SUCCESSOR)

927

EXHAUST TREATMENT, EURO 6 TECHNOLOGY

961

EXHAUST SYSTEM WITH OPF, GENERATION 2.0

969

EURO 6 TECHNOLOGY COC DOCUMENT - WITH MOTOR VEHICLE REGISTRATION CERTIFICATE, PART 2

98B

UPPER RADIATOR SHUTTERS

998

CONTROL CODE FOR CONVERSION TO WLTP WITH RDE

B10

FUEL TANK PACKAGES FOR EURO-6D STANDARD

B18

SPECTACLES COMPARTMENT

B30

CHARGING CABLE SCHUKO CEE 7/7 (TYPE E/F) 4M/5M

B53

EXTERNAL NOISE SOUND GENERATOR FOR HYBRIDS AND EV

B59

DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)

F177

MODEL SERIES 177

FV

LONG SEDAN

GA

AUTOMATIC TRANSMISSION

H59

TRIM ELEMENTS - PLASTIC IMD CARBON FIBER LOOK SILVER (2B75)

HA

REAR AXLE

JGJ

PLANT CONTROL CODE

JIT

PLANT CONTROL CODE

JWV

PLANT CONTROL CODE

K13

CONTROL CODE FOR SERVICE INTERVAL 25000 KM

K31

NOISE REGULATIONS AS PER ECE R51-03

L

LEFT-HAND DRIVE

L3E

SPORT STEERING WHEEL - SMOOTH SPLIT LEATHER

M14

DISPLACEMENT 1.4 LITER

M282

INLINE 4-CYLINDER SPARK IGNITION ENGINE M282

ME08

HYBRID DRIVE 75 KW-84 KW (90 KW-V213) VAR. (PLUG-IN)

P17

KEYLESS-GO PACKAGE

P44

PARKING PACKAGE

P49

MIRROR PACKAGE

P59

URBAN/PROGRESSIVE PACKAGE

PWG

CONTROL CODE FOR SALES

PXV

CONTROL CODE FOR SALES

PZW

CONTROL CODE FOR SALES

R01

SUMMER TYRES

U01

REAR SEAT BELT STATUS INDICATOR

U10

FRONT PASSENGER SEAT WITH WEIGHT SENSOR

U54

COMPOUND-LINK AXLE

U59

SEAT COMFORT PACKAGE

U60

PEDESTRIAN PROTECTION - ACTIVE HOOD

U62

EXTERIOR LIGHT AND SIGHT PACKAGE

V50

SPEED + LOAD INDEX 91W

VL

LEFT FRONT AXLE HALF

VR

RIGHT FRONT AXLE HALF



Surse de date

Am verificat 900+ de surse de date în **35 de țări**