

Maintenance History

Generation Date 06/03/2023

Plate Number B-30-WLF
BO Vehicle Number 1026624
Make VOLKSWAGEN **Model** PASSAT
Vehicle Description PASSAT 2.0 TDI SCR 190HP HIGHLINE DSG 4WD
Contract Number 31695

Event date	Mileage	Event description	Supplier name
11/01/2023	91372	Siguranta	
11/01/2023	91372	SAT Generic Code	
11/01/2023	91372	Bujii	
11/01/2023	91372	Bujii	
03/01/2023	91371	Ulei motor	
03/01/2023	91371	Manopera	
03/01/2023	91371	Inspectie service 5 an	
27/07/2022	81226	Ulei motor	
27/07/2022	81226	Materiale mici	
27/07/2022	81226	Materiale mici	
27/07/2022	81226	Inspectie service ulei	
27/07/2022	81226	Filtru polen	
27/07/2022	81226	Buson baie de ulei	
14/01/2022	71510	Ulei diferential	PORSCHE INTER AUTO ROMANIA SRL
14/01/2022	71510	Stand de frana	PORSCHE INTER AUTO ROMANIA SRL
14/01/2022	71510	Revizie anuala	PORSCHE INTER AUTO ROMANIA SRL
14/01/2022	71510	Materiale mici	PORSCHE INTER AUTO ROMANIA SRL
14/01/2022	71510	Lichid frana	PORSCHE INTER AUTO ROMANIA SRL

14/01/2022	71510	Inspectie service suplimentara	PORSCHE INTER AUTO ROMANIA SRL
14/01/2022	71510	Frana spate - placute	PORSCHE INTER AUTO ROMANIA SRL
14/01/2022	71510	Bec Far	PORSCHE INTER AUTO ROMANIA SRL
16/07/2021	60292	Stand de frana	
16/07/2021	60292	Materiale mici	
16/07/2021	60292	Frana fata - placute	
28/01/2021	54438	Ulei motor	PORSCHE INTER AUTO ROMANIA SRL
28/01/2021	54438	Inspectie service ulei	PORSCHE INTER AUTO ROMANIA SRL
10/09/2020	46602	Interval service flexibil	MIDOCAR SRL
10/09/2020	46602	Filtru polen	MIDOCAR SRL
10/09/2020	46602	Baterie cheie	MIDOCAR SRL
11/09/2019	27254	Ulei motor	PORSCHE INTER AUTO ROMANIA SRL
11/09/2019	27254	Materiale mici	PORSCHE INTER AUTO ROMANIA SRL
11/09/2019	27254	Interval service flexibil	PORSCHE INTER AUTO ROMANIA SRL
11/09/2019	27254	Inspectie service ulei	PORSCHE INTER AUTO ROMANIA SRL
11/09/2019	27254	Buson baie de ulei	PORSCHE INTER AUTO ROMANIA SRL