

# Maintenance and Repair Report

## BMW SERIES 2 ACTIVE ( FE804EF )

tachometer	Description	Maintained and repaired by	Date
116 526 Km	Pollen filter MAGNETI MARELLI	CARROZZERIA GILDO SRL	05/05/2021
116 526 Km	Air Filter Passenger Car -> MAGNETI MARELLI ì Fil	CARROZZERIA GILDO SRL	05/05/2021
116 526 Km	Fuel filter compl.	CARROZZERIA GILDO SRL	05/05/2021
116 526 Km	MAGNETI MARELLI oil filter	CARROZZERIA GILDO SRL	05/05/2021
116 526 Km	Helix Ultra Professional AV-L 5W30 ì Engine oil S	CARROZZERIA GILDO SRL	05/05/2021
116 526 Km	Front brake wear sensor	CARROZZERIA GILDO SRL	05/05/2021
116 526 Km	Front brake pad series. RHIAG	CARROZZERIA GILDO SRL	05/05/2021
110 670 Km	Revision management	CARROZZERIA GILDO SRL	16/09/2020
110 670 Km	Mctc revision	CARROZZERIA GILDO SRL	16/09/2020
110 670 Km	Shipping costs	CARROZZERIA GILDO SRL	16/09/2020
86 406 Km	Pollen filter KNECHT ì Pollen filter	CARROZZERIA GILDO SRL	14/10/2019
86 406 Km	Oil Filter MAGNETI MARELLI ì Oil Filter	CARROZZERIA GILDO SRL	14/10/2019
86 406 Km	Helix Ultra Professional AV-L 5W30 ì Engine oil	CARROZZERIA GILDO SRL	14/10/2019
76 708 Km	Warranty management	CARROZZERIA GILDO SRL	12/07/2019
74 779 Km	Warranty management	CARROZZERIA GILDO SRL	17/05/2019
63 513 Km	Bolt ì Wheel bolt black	CARROZZERIA GILDO SRL	20/12/2018
63 513 Km	Brake pads -> TRW ì Series brake pads pos	CARROZZERIA GILDO SRL	20/12/2018
63 513 Km	Front brake pads FDB	CARROZZERIA GILDO SRL	20/12/2018
63 513 Km	Front brake wear sensor	CARROZZERIA GILDO SRL	20/12/2018
63 513 Km	Post brake wear sensor. -> RHIAG ì Wear sensor	CARROZZERIA GILDO SRL	20/12/2018
60 110 Km	Diagne	CARROZZERIA GILDO SRL	16/10/2018
60 110 Km	Flowmeter ì Flowmeter Flowmeter	CARROZZERIA GILDO SRL	16/10/2018
60 110 Km	Fuel pressure sensor	CARROZZERIA GILDO SRL	16/10/2018
58 125 Km	Pollen filter MAGNETI MARELLI ì Pollen filter	CARROZZERIA GILDO SRL	27/09/2018
58 125 Km	Air Filter KNECHT ì Air Filter	CARROZZERIA GILDO SRL	27/09/2018
58 125 Km	Fuel filter compl. KNECHT ì Fuel filter	CARROZZERIA GILDO SRL	27/09/2018
58 125 Km	Oil filter	CARROZZERIA GILDO SRL	27/09/2018
58 125 Km	Helix Ultra Professional AV-L 0W30 -> SHELL ì Oil	CARROZZERIA GILDO SRL	27/09/2018
37 723 Km	Warranty management	CARROZZERIA GILDO SRL	10/01/2018
37 723 Km	BMW QUOTE FOR REPLACEMENT NOT WARRANTY	CARROZZERIA GILDO SRL	10/01/2018
26 911 Km	Pollen filter	CARROZZERIA GILDO SRL	04/09/2017
26 911 Km	Oil filter	CARROZZERIA GILDO SRL	04/09/2017
26 911 Km	Engine oil	CARROZZERIA GILDO SRL	04/09/2017

<b>tachometer</b>	<b>Description</b>	<b>Maintained and repaired by</b>	<b>Date</b>
0 Km	Battery	CARROZZERIA GILDO SRL	01/01/2001