

TECHNICAL VEHICLE HISTORY

Registration : **QD4025**

Contract ID : **552685**

VIN number : **WBAYL11080EG08401**

1st Circ Date : **07/06/2018**

Vehicle make : **BMW**

Vehicle type : **2.0 dA xDrive20**

Last mileage : **160.706 KM**

Distance	Event date	Vehicle part description	Supplier
107 KM	16/10/2018	JOCKEY WHEEL	PNEUS MRECHES WINDHOF
107 KM	16/10/2018	RIM	PNEUS MRECHES WINDHOF
17.416 KM	15/04/2019	AD-BLUE Filling	BILIA ARLON
17.416 KM	15/04/2019	CHECK FLUIDS	BILIA ARLON
26.995 KM	09/09/2019	AD-BLUE Filling	BILIA ARLON
26.995 KM	09/09/2019	CHECK FLUIDS	BILIA ARLON
29.095 KM	30/09/2019	AD-BLUE Filling	BILIA ARLON
29.095 KM	30/09/2019	CHECK FLUIDS	BILIA ARLON
29.095 KM	30/09/2019	Serv Intern Filter	BILIA ARLON
29.095 KM	30/09/2019	Serv Motor Oil	BILIA ARLON
39.767 KM	04/02/2020	AD-BLUE Filling	BILIA ARLON
46.350 KM	01/07/2020	CHECK FLUIDS	BILIA ARLON
48.929 KM	23/08/2020	AD-BLUE Filling	BILIA ARLON
48.929 KM	23/08/2020	CHECK FLUIDS	BILIA ARLON
59.244 KM	16/01/2021	BALAIS ES-GL AV	BILIA ARLON
59.244 KM	16/01/2021	BATTERY	BILIA ARLON
59.244 KM	16/01/2021	BMW VEH. CHECK	BILIA ARLON
59.244 KM	16/01/2021	Ser Fuel Filter	BILIA ARLON
59.244 KM	16/01/2021	Serv Air Filter	BILIA ARLON
59.244 KM	16/01/2021	Serv Intern Filter	BILIA ARLON
59.244 KM	16/01/2021	Serv Motor Oil	BILIA ARLON
61.098 KM	09/02/2021	AD-BLUE Filling	BILIA ARLON
65.406 KM	25/03/2021	PLAQ. FREIN ARR	BILIA ARLON
65.406 KM	25/03/2021	PLAQUETTES AV,	BILIA ARLON
70.886 KM	20/05/2021	LIQ. DE FREIN	BILIA ARLON
91.307 KM	08/02/2022	Serv Intern Filter	BILIA ARLON
91.307 KM	08/02/2022	Serv Motor Oil	BILIA ARLON
101.906 KM	30/09/2022	BATTERY	BILIA ARLON
101.906 KM	30/09/2022	CHECK FLUIDS	BILIA ARLON
120.432 KM	29/03/2023	BALAI ESS-GL AR	BILIA ARLON
120.432 KM	29/03/2023	BALAIS ES-GL AV	BILIA ARLON
123.446 KM	24/05/2023	AD-BLUE Filling	BILIA ARLON
123.446 KM	24/05/2023	BMW VEH. CHECK	BILIA ARLON

TECHNICAL VEHICLE HISTORY

Registration : **QD4025**

Contract ID : **552685**

VIN number : **WBAYL11080EG08401**

1st Circ Date : **07/06/2018**

Vehicle make : **BMW**

Vehicle type : **2.0 dA xDrive20**

Last mileage : **160.706 KM**

Distance	Event date	Vehicle part description	Supplier
123.446 KM	24/05/2023	LIQ. DE FREIN	BILIA ARLON
123.446 KM	24/05/2023	Ser Fuel Filter	BILIA ARLON
123.446 KM	24/05/2023	Serv Air Filter	BILIA ARLON
123.446 KM	24/05/2023	Serv Intern Filter	BILIA ARLON
123.446 KM	24/05/2023	Serv Motor Oil	BILIA ARLON
130.521 KM	02/09/2023	INLET MANIFOLD	BILIA ARLON
130.521 KM	02/09/2023	PLAQUETTES AV,	BILIA ARLON
152.040 KM	24/07/2024	BR.DISCS+PADS R	BILIA ARLON
152.040 KM	24/07/2024	Serv Intern Filter	BILIA ARLON
152.040 KM	24/07/2024	Serv Motor Oil	BILIA ARLON
160.035 KM	19/10/2024	BATTERY	BILIA ARLON
160.706 KM	01/11/2024	DIAGNOSIS	BILIA ARLON

Unitatea : S.C. Parts Auto Glob S.R.L.
Nr înregistrare fiscal RO12706078
Nr Reg Com J03/51/2000
Localitatea Pitesti
Cont RO51INGB0000999901882850
Banca ING

Adresa B-dul Republicii nr. 156
Tel/Fax 0755 115961
Pers. de contact Grigore Vlad

COMANDA DEVIZ Nr
la data de 07.08.2025
Termen de executie 2 ORE

Pe baza Cererii nr. din ##### TELEFON 0724050741 Cota TVA % 21%

Client: TITANIC GRUP LOGISTI Adresa: Pitesti

Lucrari solicitate de client REVIZIE

MECANIC; Stroe Ionut

Reprezentant autorizat -mecanica Serbanescu Ionut

Nr de inmatriculare: Autovehicul: BMW X2 Km parcursi: 169700

Numar de ident VIN WBAYL11080EG08401 Tip motor Cilindree cm3 2000

Categoria Putere (KW)

Caroseria Sursa de energie DIESEL

Anul fabricaiei 2018

144 6 Ron fara TVA		Manopera							
Nr.	Cod catalog	Denumire	Pret de lista unitar fara TVA [lei/h]	UM (H)	Durata (H)	Disc %	Pret unitar Special fara TVA	Valoare fara TVA	
1		MAN INL ULEI + FILTRE	144 62	H	1 15	0%	145	166 31	
2									
3									
4									
5									
6									
7									
8									
9									
10									

0% - Discount		Articole							
Nr	Cod articol	Denumire	Pret unitar fara TVA	UM	Cantitatea	Disc %	Pret unitar Special fara TVA	Valoare fara TVA	
1	1142853186	FILTRU ULEI	74 38	BUC	1	0%	74 38	74 38	
2	E1280L	FILTRU AER	95 04	BUC	1	0%	95 04	95 04	
3	PC3047AG	FILTRU POLEN	70 24	BUC	1	0%	70 24	70 24	
4	KL983D	FILTRU MOTORINA	148 76	BUC	1	0%	148 76	148 76	
5	5W-30	ULEI BMW 5W-30 1L	74 38	BUC	5	0%	74 38	371 90	
6				BUC					
7				BUC					
8				BUC					
9				BUC					
10				BUC					
11				BUC					
12				BUC					
13				BUC					
14				BUC					
15				BUC					

Manopera	166 31	TVA Manopera	34 93	Total Manopera:	201 24
Piese si Materiale	760 32	TVA Piese	159 67	Total Piese Si Materiale:	919 99
Comanda Deviz	926 63	TVA Deviz	194 59	Total Deviz:	1,121 23

Asiguratorul Nr dosar de dauna

Pentru reparatiile executate cu piesele clientului nu se acordă garanție

Lucrările corespund calitativ Am primit autoturismul reparat și cu inventarul complet
Sef service Semnătura CLIENT

Se certifică garanția la lucrare conform LG449/2003 la data devizului de mai sus și documentelor însoțitoare
Certificat garanție LG449/2003

- 1) Garanția pentru manopere este de 3 luni cu condiția ca autovehiculul să fie exploatat conform indicațiilor din manualul de exploatare al producătorului
- 2) Garanția la piesele de folosință îndelungată este de 18 luni 60000KM
- 3) Garanția se acordă numai la piesele comercializate de către unitatea noastră
- 4) Service-ul își rezervă dreptul de retenție asupra mașinii până la achitarea acesteia