



Škoda Superb

VIN: TMBLJ7NP4K7027379

Diesel

2018

Generat pe 2024-11-14 15:11



Contor de parcurs

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Fotografii

2024-01

56 de fotografii









Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?

✓ Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.

i Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în **9 țări**:  +3

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Danemarca



Lituania



Statele Unite ale Americii



Slovacia



Slovenia



Suedia



Cehia




Finlanda

Contor de parcurs

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?

i Notă

Ultimul kilometraj cunoscut: 161.921 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Notă

Inspecția tehnică a fost transmisă pe 2023-01 în  **Italia**

Legal



Inspecție tehnică periodică (ITP)

A trecut 2023-01



A trecut cu succes inspecția tehnică
Valabil până la 2025-01



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?



Ai grijă!

Acest vehicul a fost avariat



Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



2024-01



Daune

Costul estimativ al reparațiilor

Necunoscut

Cauza posibilă a daunelor

Necunoscut

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviceurile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Dezastru natural

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Emisii


Câte emisii de CO2 produc vehiculele din acest model/an?



Notă

Emisii CO2: E (171 g/km)

Emisii CO₂



Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?



Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Škoda



Model

Superb



Tip caroserie

Break



An de fabricație

2018



An model

2019



Capacitate cilindrică

2 l



Putere motor

140 kW (188 cp)



Tip combustibil

Diesel



Cutie de viteze

Automată



Tip transmisie

Tracțiune integrală (AWD)



Culoare

Gri



Nr. uși

5



Amplasarea volanului

Volan pe stânga



Nr. cilindri

4



Nr. angrenaje

7

Echipare

Cum a fost primit de la producător

0B5

WHEELBASE

0F5

FUEL SYSTEM FOR DIESEL ENGINE

0FA

STANDARD MANUFACTURING SEQUENCE

0IJ

INSTALLATION DIFFERENTIATION FOR TRANSMISSION "DQ381" -- VEHICLE COMPONENTS --

0K0

WITHOUT ALTERNATIVE DRIVE SYSTEM

0M4

FUEL TANK

0P0

REAR EXHAUST TAILPIPE (STANDARD)

0SC

LABELS/PLATES IN ENGLISH

0TD

FLOOR MATS IN FRONT AND REAR

0VG

INFORMATION KIT IN ITALIAN

0Y1

STANDARD CLIMATIC ZONES

0YE

WEIGHT RANGE 5 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

1AT

ELECTRONIC STABILITY CONTROL (ESC)

1D0

WITHOUT TRAILER HITCH

1E9

WITHOUT ACTIVATED CARBON CANISTER WITH SCR

1EX

SPECIAL IDENTIFICATION PLATE FOR EC FOR M1 PASSENGER VEHICLE

1G9

SPACE-SAVING SPARE WHEEL FOR TEMPORARY USE, RADIAL TIRE (5-HOLE)

1JA

REAR SHOCK ABSORPTION, BASIC VERSION 1

1KU

DISK BRAKES IN REAR

1N3

SPEED-RELATED VARIABLE STEERING ASSIST (SERVOTRONIC)

1NL

TRIMS FOR ALLOY WHEELS

1PF

STANDARD WHEEL BOLTS

1Q3

MASS DAMPER FOR STEERING WHEEL, XX HZ

1S1

TOOL KIT AND JACK

1SA

WITHOUT ADDITIONAL FRONT UNDERBODY GUARD

1X1

FOUR WHEEL DRIVE

1Y3

ELECTRONIC DIFFERENTIAL LOCK XDS DYNAMIC TRACTION CONTROL

1Z0

INITIAL STANDARD FUEL FILLING

1ZA

DISK BRAKES IN FRONT

20A

WITHOUT ELECTRIC MOTOR (HYBRID)

2A0

WITHOUT DELIVERY EQUIPMENT

2B1

ADDITIONAL EXTERIOR NOISE SUPPRESSION

2H0

WITHOUT "DRIVE SELECT"

2JV

BODY-COLORED BUMPERS

2PU

LEATHER-WRAPPED MULTIFUNCTION SPORTS STEERING WHEEL

2WA

WITHOUT ADDITIONAL TIRES

3B4

CHILD SEAT ANCHOR FOR CHILD SEAT SYSTEM ISOFIX

3C7

3-POINT SEAT BELT FOR CENTER REAR SEAT

3CX

NET PARTITION

3D2

CENTER CONSOLE

3FA

WITHOUT ROOF INSERT (STANDARD ROOF)

3G2

CHILD SEAT ANCHOR, FRONT RIGHT (ISOFIX)

3GN

VARIABLE CARGO AREA

3H0

WITHOUT BACKREST RELEASE FOR FRONT SEATS

3LC

DOOR AND SIDE TRIM PANEL IN FOAM FILM AND WOVEN FABRIC

3N2

STORAGE COMPARTMENTS WITH COVER IN TRUNKSIDE PANEL

3NU

REAR SEAT BENCH UNSPLIT, BACKREST SPLIT FOLDING WITH CENTER ARMREST

3PH

POWER SEAT ADJUSTMENT WITH MEMORY FEATURE FOR LEFT SEAT, RIGHT SEAT MANUALLY HEIGHT-ADJUSTABLE

3QT

3-POINT SEAT BELTS IN FRONT, WITH PRETENSIONER AND HEIGHT ADJUSTMENT

3S9

ROOF RAILS

3T2

THREE REAR HEAD RESTRAINTS

3U1

FOLDING TRUNK COVER

3W3

SPECIAL INTERIOR NOISE SUPPRESSION

3X0

WITHOUT LOAD-THROUGH HATCH

3Y0

WITHOUT ROLL-UP SUNSHADE

3ZU

3-POINT SEAT BELTS, OUTER REAR WITH ECE LABEL

4A0

WITHOUT SEAT HEATER

4D0

WITHOUT SEAT VENTILATION/MASSAGE SEAT

4E2

TAILGATE/TRUNK LID RELEASE FROM INSIDE (ELECTRICALLY)

4GF

WINDSHIELD IN HEAT-INSULATING GLASS

4H5

POWER-OPERATED CHILD SAFETY LOCK

4K3

RADIO REMOTE CONTROLLED CENTRAL LOCKING OPERATED FROM INSIDE AND SAFELOCK

4KF

SIDE WINDOWS IN HEAT-INSULATING GLASS, FROM B-PILLAR AND REAR WINDOW DARK TINTED

4L6

BREAKAWAY INTERIOR REARVIEW MIRROR, AUTO-DIMMING

4UP

DRIVER AND FRONT PASSENGER AIRBAG WITH KNEE AIRBAG AND FRONT PASSENGER AIRBAG DEACTIVATION

4V0

WITHOUT FRONT PASSENGER SEAT CONTROL

4X3

SIDE AIRBAG IN FRONT, WITH CURTAIN AIRBAG

4ZB

BRIGHT MOLDINGS

5C0

WITHOUT SPECIAL BODY MEASURES

5D1

CARRIER FREQUENCY 433.92 MHZ-434.42 MHZ

5J3

ROOF SPOILER

5K5

TRANSIT COATING FILM WITH ADDITIONAL TRANSPORT PROTECTION MEASURES

5MB

DECORATIVE INSERTS

5RQ

RIGHT EXTERIOR MIRROR, CONVEX

5SJ

LEFT EXTERIOR MIRROR, CONVEX

5XI

SUN VISORS WITH MIRROR, ILLUMINATED, AIRBAG LABEL ON SUN VISOR

5ZF

FRONT HEAD RESTRAINTS

6A0

WITHOUT FIRE EXTINGUISHER

6E7

CENTER ARMREST IN FRONT

6FF

BODY-COLORED EXTERIOR MIRROR HOUSINGS AND VARIOUS ADD-ON PARTS

6K3

FORWARD COLLISION WARNING INCL. AUTONOMOUS EMERGENCY BRAKING, FOR ADAPTIVE CRUISE CONTROL
"LOW"

6KJ

RADIATOR GRILLE WITH CHROME MOLDING

6M3

TRUNK NET

6N0

WITHOUT MUD FLAP

6NA

UNSPLIT MOLDED HEADLINER

6Q2

LEATHER GEARSHIFT KNOB/HANDLE

6T2

INTERIOR LIGHT IN FOOTWELL IN FRONT AND REAR

6XT

EXTERIOR MIRRORS WITH MEMORY FEATURE, AUTO-DIMMING, POWER-FOLDING/ADJUSTABLE, SEPARATELY
HEATED

77G

DATA STORAGE DEVICE FOR EU, INTEGRATED

7AL

ANTI-THEFT ALARM SYSTEM, INTERIOR MONITORING, BACKUP HORN, AND TOWING PROTECTION

7B3

12-VOLT SOCKET(S)

7E0

WITHOUT HEAT ACCUMULATOR/AUXILIARY HEATER

7K1

DIRECT TIRE PRESSURE MONITORING SYSTEM

7L6

START/STOP SYSTEM WITH REGENERATIVE BRAKING

7M4

SCUFF PLATES IN DOOR APERTURES

7P7

POWER-ADJUSTABLE LUMBAR SUPPORT FOR LEFTFRONT SEAT

7U0

STANDARD ENGINE STARTER

7UG

NAVIGATION SYSTEM - HIGH

7W0

WITHOUT EXTENDED SAFETY SYSTEM

7X2

PARK DISTANCE CONTROL IN FRONT AND REAR

7Y9

BLIND SPOT MONITOR AND LANE KEEPING SYSTEM

7ZU

VEHICLE CLASS DIFFERENTIATION 3V0

8FA

WITHOUT SECOND BATTERY

8G3

ADVANCED HIGH-BEAM CONTROL

8GU

ALTERNATOR 140 A

8IP

GAS-DISCHARGE HEADLAMPS WITH VARIABLE LIGHT DISTRIBUTION

8K3

SEPARATE DAYTIME RUNNING LIGHTS WITH AUTOMATIC HEADLAMP ACTIVATION AND COMING HOME FEATURE

8M1

REAR WINDOW WIPER AND WASHER SYSTEM WITH INTERMITTENT CONTROL

8N6

WINDSHIELD WIPER INTERMITTENT CONTROL WITH LIGHT/RAIN SENSOR

8Q5

HEADLIGHT RANGE ADJUSTMENT, AUTOMATIC/ DYNAMIC, WITH CORNERING LIGHT (AFS 1)

8RM

8 SPEAKERS (PASSIVE)

8S4

TWO READING LIGHTS IN FRONT, TWO IN REAR

8SK

LED TAIL LAMP ASSEMBLY

8T8

ADAPTIVE CRUISE CONTROL (WITH "FOLLOW-TO-STOP") AND SPEED LIMITER

8TB

REAR FOG LAMP

8WH

FRONT FOG LAMP AND CORNERING LAMP

8X1

HEADLAMP WASHER SYSTEM

8Y1

TWO-TONE HORN

8Z5

NOT HOT COUNTRY

8ZQ

ANTENNA FOR FM RECEPTION ONLY, DIVERSITY

9AK

CLIMATRONIC WITH IMPACT PRESSURE CONTROL, CFC-FREE

9D0

WITHOUT PREPARATION FOR TWO-WAY RADIO INSTALLATION

9E1

LUGGAGE COMPARTMENT LIGHTING

9HA

WITHOUT ADDITIONAL MALFUNCTION DISPLAY

9IM

TELEPHONY (RSAP) AND LTE (WITH WLAN)

9JB

SMOKER'S PACKAGE, ASHTRAY IN FRONT AND REAR

9M0

WITHOUT AUXILIARY HEATER/FUEL-FIRED PARKING HEATER

9P5

VISUAL AND ACOUSTIC SEAT BELT REMINDER, ELECTRIC CONTACT

9S5

MULTI-FUNCTION DISPLAY/ON-BOARD COMPUTER"MEDIUM"

9T1

HEATED WASHER NOZZLES IN FRONT

9TD

WARNING LIGHTS IN FRONT DOORS AND RETRO-REFLECTORS IN REAR DOORS

9WT

MIRRORLINK

9Z3

12-V OPERATING VOLTAGE AND 230-V INVERTER

A61

CATEGORY 1

A8C

COMFORT EQUIPMENT

AV1

DRIVING ON THE RIGHT

B0A

COMPONENT PARTS SET WITHOUT COUNTRY-SPECIFIC BUILDING REGULATION

B14

TYPE APPROVAL COUNTRY ITALY (SAN MARINO, VATICAN CITY)

C49

OPERATING PERMIT, ALTERATION

C6U

ALLOY WHEELS 7J X 17

DE5

4-CYL. TURBO DIESEL ENGINE 2.0 L/140 KW (4V) TDI COMMON RAIL BASE ENGINE IS TD1/TR1/T5S/T6F

E0A

NO SPECIAL EDITION

EA0

WITHOUT FOLLOW-ON WARRANTY

EF0

WITHOUT ECO FUNCTION

EL5

ONLINE SERVICE, WITH OCU, WITH HEAD UNITCODING, WITHOUT ENGINE IMMOBILIZER INTERCONNECTION

EM1

DRIVER ALERT SYSTEM

ER1

REGIONAL CODE " ECE " FOR RADIO

ES0

WITHOUT VEHICLE INLET

EV0

WITHOUT CHARGING CABLE

F0A

NO SPECIAL PURPOSE VEHICLE, STANDARD EQUIPMENT

FB0

STANDARD PAINT COATING

FM0

BASIC EQUIPMENT VARIANT

G01

SHOCK ABSORPTION IN FRONT

G1D

7-SPEED AUTOMATIC TRANSMISSION FOR FOUR-WHEEL DRIVE

GM1

STANDARD ELECTRONIC ENGINE SOUND

H5C

TIRES 215/55 R17 94W

I8J

RADIO HIGH (GEN2 GP)

IA1

WITH BRACKET

J2D

BATTERY 380 A (68 AH)

K8D

WAGON/AVANT

KA0

WITHOUT CAMERA SYSTEMS/ACCIDENT SENSORS

KK3

REFRIGERANT R1234YF

KS0

WITHOUT HEAD-UP DISPLAY

L08

SUSPENSION RANGE 08 INSTALLATION CONTROL ONLY, NO REQUIREMENT FORECAST

L0L

LEFT-HAND DRIVE

N0D

SEAT TRIM COVERS IN FABRIC

ND0

WITHOUT ADAPTER

NZ4

PRIVATE EMERGENCY CALL SYSTEM

Q2J

COMFORT SEATS IN FRONT

QA0

WITHOUT CHILD SEAT

QG1

SERVICE INTERVAL PROLONGATION

QH3

VOICE CONTROL AND VOICE ENHANCER

QI6

SERVICE INDICATOR 30 000 KM OR 2 YEARS (VARIABLE)

QJ1

CHROME PACKAGE

QK1

WITH MULTIFUNCTION CAMERA

QN2

DRAWER UNDER RIGHT FRONT SEAT

QQ0

WITHOUT ADD. LIGHTS (INTERIOR LIGHTING)

QR9

WITH DYNAMIC ROAD SIGN DISPLAY

QV3

DIGITAL RADIO RECEPTION

TR1

4-CYLINDER DIESEL ENGINE 2.0 L UNIT 04L.A

U5A

INSTRUMENT CLUSTER, KM/H SPEEDOMETER

UG1

HILL START ASSIST

UH2

PARKING BRAKE

UK1

STANDARD REAR SEAT RELEASE

UP1

DIGITAL CLOCK

UQ5

ELECTRIC INTERFACE FOR EXTERNAL USE, 2 X USB

V0A

TIRES WITHOUT SPECIFICATION OF TIRE BRAND

VC0

WITHOUT REMOTE-CONTROLLED GARAGE DOOR OPENER

VF0

STANDARD PEDAL CLUSTER

VL1

EXTENDED PEDESTRIAN PROTECTION MEASURES

X4C

EQUIPMENT OPTIONS SUBSET FOR ITALY

Cronologie

S-au găsit 8 înregistrări

Cronologia înregistrărilor pentru acest vehicul

Ultimele înregistrări

2019-01

 Țară necunoscută



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2019-01

 Țară necunoscută



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2020-11

 Italia



Proprietarul s-a schimbat

Țara (sau statul) a indicat locația geografică a unei schimbări sau reînnoiri documentate de proprietar. Vă rugăm să rețineți că unele modificări pot fi formale, de exemplu, transferurile de la sfârșitul contractului de leasing sau situații similare.

2023-01

 Italia



A fost verificat

A fost înregistrat un eveniment de inspecție tehnică (cunoscut și sub denumirea de ITP, test tehnic sau test de control al emisiilor). Pot fi incluse atât instanțe reușite, cât și eșuate.

2024-01

 Italia



Daună detectată

Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.

2024-01

 Italia



A fost la vânzare

Această înregistrare a fost creată deoarece vehiculul a fost listat pentru vânzare pe o anumită piață. Uneori, țara (sau statul) vânzătorului suprascrie locația reală a vehiculului.

2024-01

 Italia



Mașină radiată

Înregistrarea indicată reprezintă un eveniment administrativ. Acesta ar putea fi legat de o schimbare de proprietar, o schimbare a documentelor sau o chestiune similară.

2024-04

 România



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**